## **Hydrant Inspection Report**

Docket No. 01-0492 ICC Staff Exh. 1.01

pg. 1 of 2

System: Wonder Lake Water Company

		1997	2001	
Hydrant #	Location	Gals. per min.	Gals. per min.	Comments
16	Near Ridge Rd. & Acorn Path	630	790	a) Increase height of hydrant (18" to middle of Cap)
				b) Hydrants requires painting;
17	Westwood Dr. & Coral Rd.	630	920	a) Hydrants requires painting;
18	West Lake Shore Dr. & Acorn	630	700	a) Hydrant needs replacing;
				Hard to open & shakes when in operating
15	Between Alden & Coral on Greenwood Drive	580	800	
14	Between Alden & Dorr on Woodstock	770	840	a) Hydrant requires painting;
13	Between Alden & Dorr on Westwood Dr.			a) Hydrant needs replacing; does not operate
10	Between Burton & Dorr on Greenwood Dr.	730	820	a) Hydrant requires painting;
12	Ridge Road		700	Increase height of hydrant (18" to middle of cap)
11	Between Alden & Dorr on Thompson Rd.	650	No Flow test	a) Hydrant requires painting;
				b) Hydrant needs repair
8	Burton Road & Ridge Drive	690	840	a) Hydrant requires painting;
				b) Hydrant hard to operate.

Note: No change from last inspection

	a: a a al
ĸ	
ı 🔪	evised

## **Hydrant Inspection Report**

Docket No. 01-0492

ICC Staff Exh. 1.01

System: Wonder Lake Water Company

pg. 2 of 2

-		1997	2001	F3
Hydrant #	Location	Gals. per min.	Gals. per min.	Comments
6	Riley Road	760	1000	a) Hydrant requires repair- Hard to operate (operated by hydrant valve)
9	West Lake Shore Dr. & Nunda Rd.	730	700	a) Hydrant requires replacing-does not shut off.
4	Between Garrison Rd. & Greenwood Dr. on West Lake	630	700	
7	Between Riley Rd. & Garrison Rd. on Greenwood Dr.	630	920	a) Repair hydrant - Hard to operate
				b) Hydrant chains needs fixing.
5	Garrison Road.	630	840	a) paint hydrant
1	West Lake Shore dr.	630	650	a) paint hydrant
2	Westwood Dr. ( 4107)			a) Replace hydrant - cracked barrel;
				b) paint hydrant.
	Westwood Dr. ( 4405)		040	a) language bainkt of budgaget (iOll to uniddle of ann)
3	Westwood Dr. ( 4125)			a) Increase height of hydrant (i8" to middle of cap).
				b) paint hydrant.

NO change from last inspection